MPIC/TDS/D-610-67 5 January 1967

MEMORANDUM FOR: Chief, Development Staff, TDS

THROUGH:

Chief, Exploitation Systems Branch

SUBJECT:

Checkout of Equipment

25X1

25X1

25X1

25X1

25X1

1. The problems associated with the equipment set up off line with the comparator appear to have been solved.

has checked out the system and determined that the major fault lies with the power supply to the converter. This fault has been corrected by adding a capacitor in each counter to smooth out the ripples. Other less serious anomolies were uncovered during the checkout indicating poor quality control by It is therefore recommended that all components at MPIC be checked out before making them operational.

25X<sup>2</sup>

25X

25X1

25X

25X

25X

25X

25X

25X

2. Althoughtthe equipment is still under warranty, it would be impractical to send all the components back to the factory for checkout is willing to undertake the checkout and perform the work at NPIC. The time estimate for checkout is 4 men days per system or 224 man hours to checkout all the on/off line equipment. This work would be accomplished by two technicians working in a non operational area such as the shop. The current task order with will cover this work. The hourly rate for a an electronic specialist is technician is mend that be given this task and that be reprimanded. should be forced or threatened to pay the bill for If practical, the work performed by There is a possibility that would be willing to send one or their own technicians to accomplish this task. If they would do this, I would recommend allowing them to correct their mistakes. Attached is a list of anomolies uncovered by

25X1A

## **Declass Review by NIMA / DoD**

Exploitation Systems Branch, DS

Attachment:

List of Malfunctions

Distribution:

Original Addresses 2002/01/02 PA HDP/8804747A00230004000



## Approved For Belease 2072/D170817GIA/RDP78B0474ZA002300040006-7

SYNCRONIZER 25X1A RTS Generator 25X1A 1. Diode CR 12 shorted out by printed circuit. 25X1A CTS Card 1. Diode from base of Q1 to ground is on board but not shown on drawing. (Remove) 25X1A Error-Acuum Logic Capacitor Cl2 shorted. 25X1A RTS Gen. Capacitor C8 connected to wrong side of Xener diode on Board (Change). 25X1A 27 capacitors for shorts. Recommend change these. Check all cards for shorts on printed circuit board and check that contacts are clean. 25X1A COUNTER 25X1A 1. Pin 8 is the-18v supply for the optisyn converter. supply has about .7V of 120 cps ripple. I have installed 100 MFD capacitor on this card (to ground from Pin 8). However, I have ordered 500 MFD capacitor at 25V because there is already a mounting hole in the counter, for this size capacitor. The con-25X1A verter calls for - 18V with no more than 10 MV ripple. The signal going into the converter is only + 130 MV. 25X1A CONTROL PANEL

- 1. Wire reversed on nixie light.
- 2. Readout buttons malfunction regularly.
- 3. Preset & zero reset buttons reversed. Also zero reset buttons are not glued.